2008 BODY & ACCESSORIES Symptom Troubleshooting [Power Window System (Exterior Open/Close Function)] - Mazda CX-9

#### 2008 BODY & ACCESSORIES

Symptom Troubleshooting [Power Window System (Exterior Open/Close Function)] - Mazda CX-9

# SYMPTOM TROUBLESHOOTING CHART [POWER WINDOW SYSTEMS (EXTERIOR OPEN/CLOSE FUNCTION)]

#### SYMPTOM TROUBLESHOOTING CHART

NO.	TROUBLESHOOTING ITEM	PAGE
1	Door glass does not operate even through various operation are performed	(See NO.1 UNABLE TO COMMUNICATE WITH GENERIC ELECTRONIC MODULE (GEM) [POWER WINDOW SYSTEMS (EXTERIOR OPEN/CLOSE FUNCTION)].)
2	Door glass does not operate using the keyless transmitter	(See NO.2 DOOR GLASS DOES NOT OPERATE USING THE KEYLESS TRANSMITTER [POWER WINDOW SYSTEMS (EXTERIOR OPEN/CLOSE FUNCTION)].)
3	Door glass does not operate using the request switch	(See NO.3 DOOR GLASS DOES NOT OPERATE USING THE REQUEST SWITCH [POWER WINDOW SYSTEMS (EXTERIOR OPEN/CLOSE FUNCTION)].)
4	Passenger door glass do not operate	(See NO.4 PASSENGER DOOR GLASS DOES NOT OPERATE [POWER WINDOW SYSTEMS (EXTERIOR OPEN/CLOSE FUNCTION)].)
5	Door glass stops before fully opening/closing	(See NO.5 DOOR GLASS STOPS BEFORE FULLY OPENING/CLOSING [POWER WINDOW SYSTEMS (EXTERIOR OPEN/CLOSE FUNCTION)].)
6	Door glass reverse before it fully opens	(See NO.6 DOOR GLASS REVERSES BEFORE IT FULLY OPENS [POWER WINDOW SYSTEMS (EXTERIOR OPEN/CLOSE FUNCTION)].)
7	Driver and passenger door glasses operate accidentally	(See NO.7 DRIVER AND PASSENGER DOOR GLASSES OPERATE ACCIDENTALLY [POWER WINDOW SYSTEMS (EXTERIOR OPEN/CLOSE FUNCTION)].)
8	Passenger door glass operates accidentally	(See NO.8 PASSENGER DOOR GLASS OPERATES ACCIDENTALLY [POWER WINDOW SYSTEMS (EXTERIOR OPEN/CLOSE FUNCTION)].)

# QUICK DIAGNOSTIC CHART [POWER WINDOW SYSTEMS (EXTERIOR OPEN/CLOSE FUNCTION)]

2008 BODY & ACCESSORIES Symptom Troubleshooting [Power Window System (Exterior Open/Close Function)] - Mazda CX-9

							X: A	Applied
	1	2	3	4	5	6	7	8
Possible factor  Troubleshooting item	Door glass does not operate even though various operations are performed	Door glass does not operate using the keyless transmitter	Door glass does not operate using the request switch	Passenger's door glass do not operate	Door glass stops before fully opening/closing	Door glass reverses before it fully opens	Driver's and passenger's door glasses operate accidentally	Passenger's door glass operates
Power window main switch malfunction	Х				Х		Х	
Power window subswitch (passenger's) malfunction				Х	Х		Х	Х
Power window motor malfunction	Х			X	Х	Х		
Battery malfunction (low voltage)	Х			Х	Х	X		
Power window system initial setting error	Х			X	Х			
Open circuit in wiring harness between power window main switch and BCM	х							
BCM malfunction	Х	х	Х		Х		Х	
Advanced keyless control module malfunction			Х					
Keyless control module malfunction		Х	Х					
Open circuit in wiring harness between keyless receiver and BCM		х	х					
Any door or liftgate is open.		х	Х					
Key is inserted in steering lock.		X	Х					
Open circuit in wiring harness between request switch and keyless control module.			х				х	
Start knob is in a position other than LOCK position.			Х					
Open circuit in wiring harness between power window main switch and power window subswitch				х			х	
Improper installation of door glass					х	Х		
Keyless entry system signal reception error (outside operation area, radio signal interference)					х			
Transmitter malfunction							Х	
Request switch malfunction							Х	
Power window main switch malfunction							Х	
Power window subswitch malfunction							х	Х

acxuuw00000957

Fig. 1: Troubleshooting Chart Courtesy of MAZDA MOTORS CORP.

#### NOTE:

- The exterior open/close function does not operate when the following conditions are met.
  - o Any door or liftgate is open.
  - o The key is inserted in the steering lock.
  - o The start knob is not in the LOCK position.
- The auto-open/close function (the exterior open/close function) does not operate if the power window initialization procedure has been reset.

2008 BODY & ACCESSORIES Symptom Troubleshooting [Power Window System (Exterior Open/Close Function)] - Mazda CX-9

• Depending on the temperature and battery conditions, the window may reverse on rare occasions.

# NO.1 UNABLE TO COMMUNICATE WITH GENERIC ELECTRONIC MODULE (GEM) [POWER WINDOW SYSTEMS (EXTERIOR OPEN/CLOSE FUNCTION)]

#### POSSIBLE CAUSE CHART

1	Door glass does not operate even though various operations are performed							
POSSIBLE CAUSE	<ul> <li>Power window main switch malfunction</li> <li>Power window motor malfunction</li> <li>Battery malfunction (low voltage)</li> <li>power window initialization procedure error</li> <li>Open circuit in wiring harness between power window main switch and BCM</li> <li>BCM malfunction</li> </ul>							

#### **DIAGNOSTIC PROCEDURE**

Step	Inspection		Action
1	<ul> <li>Inspect the operation of the door glass by operating the power window main switch.</li> <li>Is the manual operation normal?</li> </ul>		Go to the next step.  Inspect the following parts, and repair or replace.  • Power window main switch  (See POWER WINDOW MAIN SWITCH INSPECTION .)  • Power window motor  (See POWER WINDOW MOTOR INSPECTION .)  • Battery (low voltage)
2	<ul> <li>Inspect the operation of the door glass by operating the power window main switch.</li> <li>Does the door glass operate in auto?</li> </ul>		Go to the next step.  Perform the power window initialization procedure.  (See POWER WINDOW INITIALIZATION PROCEDURE .)
3		Yes	Inspect the wiring harness between the power window main switch and the BCM. If there is any malfunction, repair or replace the applicable part.

2008 BODY & ACCESSORIES Symptom Troubleshooting [Power Window System (Exterior Open/Close Function)] - Mazda CX-9

		Replace the BCM.
<ul> <li>Does the door lock/unlock normally?</li> </ul>	No	(See <b>BODY CONTROL MODULE (BCM)</b>
3		<u><b>REMOVAL/INSTALLATION</b></u> .)

# NO.2 DOOR GLASS DOES NOT OPERATE USING THE KEYLESS TRANSMITTER [POWER WINDOW SYSTEMS (EXTERIOR OPEN/CLOSE FUNCTION)]

### POSSIBLE CAUSE CHART

2	DOOR GLASS DOES NOT OPERATE USING THE KEYLESS TRANSMITTER						
POSSIBLE CAUSE	<ul> <li>Keyless control module malfunction</li> <li>BCM malfunction</li> <li>Open circuit in wiring harness between keyless control module and BCM</li> <li>Any door or liftgate is open</li> <li>Key is inserted in steering lock</li> </ul>						

#### **DIAGNOSTIC PROCEDURE**

Step	Inspection		Action
1	<ul> <li>Inspect the door lock/unlock operation using the transmitter.</li> <li>Does it operate normally?</li> </ul>		Inspect the following parts, and repair or replace.  • BCM  (See <u>BODY CONTROL MODULE</u> (BCM) INSPECTION .)  • Keyless control module (Vehicles with advanced keyless system)  (See <u>KEYLESS CONTROL MODULE</u> INSPECTION [ADVANCED KEYLESS SYSTEM] .)
		No	Go to the next step.
2	<ul> <li>Inspect the open/close condition of the doors and the liftgate.</li> <li>Is the reason why they do not</li> </ul>	Vac	System is normal (Does not operate when a door or the liftgate is open).
	lock/unlock because a door or the	No	Go to the next step.
	<ul> <li>Verify whether the key is in the steering lock.</li> </ul>	Yes	System is normal (Does not operate when the key is inserted in the steering wheel lock)

2008 BODY & ACCESSORIES Symptom Troubleshooting [Power Window System (Exterior Open/Close Function)] - Mazda CX-9

3	<ul> <li>Is the reason why they do not lock/unlock because the key is inserted in the steering lock?</li> </ul>	No	Go to the next step.
4	When the lock/unlock operation does not operate for reasons other than the above Steps 2 and 3.	Yes	<ul> <li>Inspect the following parts, and repair or replace.</li> <li>Keyless control module         (See <u>KEYLESS CONTROL MODULE INSPECTION [ADVANCED KEYLESS SYSTEM]</u>)     </li> <li>Wiring harness between keyless control module and BCM.</li> <li>Reinspect for malfunction recurrence. If the</li> </ul>
		No	malfunction is not corrected, repeat the procedure from Step 1.

# NO.3 DOOR GLASS DOES NOT OPERATE USING THE REQUEST SWITCH [POWER WINDOW SYSTEMS (EXTERIOR OPEN/CLOSE FUNCTION)]

#### POSSIBLE CAUSE CHART

3	Door glass does not operate using the request switch						
	<ul><li>Keyless control module malfunction</li><li>BCM malfunction</li></ul>						
POSSIBLE CAUSE	<ul> <li>Open circuit in wiring harness between request switch and keyless control module.</li> </ul>						
CAUSE	Any door or liftgate is open.						
	Key is inserted in steering lock.						
	Start knob is in a position other than LOCK position.						

#### **DIAGNOSTIC PROCEDURE**

Step	Inspection		Action
1	<ul> <li>Verify the door lock/unlock operation by operating the request switch.</li> <li>Does it operate normally?</li> </ul>	Yes	Inspect the following parts, and repair or replace.  • Keyless control module  (See KEYLESS CONTROL MODULE INSPECTION [ADVANCED KEYLESS SYSTEM] .)  • BCM

2008 BODY & ACCESSORIES Symptom Troubleshooting [Power Window System (Exterior Open/Close Function)] - Mazda CX-9

			(See <u>BODY CONTROL MODULE</u> (BCM) INSPECTION .)
		No	Go to the next step.
2	<ul> <li>Verify the open/close condition of the doors and the liftgate.</li> <li>Is the reason why they do not</li> </ul>	Yes	The system is normal (When any door or the liftgate is open, the system does not operate).
	lock/unlock because a door or the liftgate is open?	No	Go to the next step.
3	<ul> <li>Verify the start knob position, or if the key is in the steering lock.</li> <li>Is the reason why the door lock/unlock does not operate because</li> </ul>		The system is normal (When the start knob is in a position other than LOCK, or the key is inserted in the steering lock, the system does not operate).
	the start knob is in a position other than LOCK, or the key is inserted?	No	Go to the next step.
4	• The door lock/unlock does not operate for reasons other than Steps 2 and 3 above.	Yes	• Wiring harness between the request switch and the keyless control module.
		No	Reinspect for malfunction recurrence. If the malfunction is not corrected, repeat the procedure from Step 1.

# NO.4 PASSENGER DOOR GLASS DOES NOT OPERATE [POWER WINDOW SYSTEMS (EXTERIOR OPEN/CLOSE FUNCTION)]

#### POSSIBLE CAUSE CHART

4	Passenger door glass does not operate					
	Power window subswitch (passenger side) malfunction					
	Power window motor malfunction					
POSSIBLE	Battery malfunction (low voltage)					
CAUSE	Open circuit in wiring harness between power window main switch and power window subswitch (passenger side)					
	power window initialization procedure error					

2008 BODY & ACCESSORIES Symptom Troubleshooting [Power Window System (Exterior Open/Close Function)] - Mazda CX-9

## **DIAGNOSTIC PROCEDURE**

Step	Inspection		Action
		Yes	Go to the next step.
			Inspect the following parts, and repair or replace.
	Inspect the door glass operation by operating the power window		Power window subswitch (passenger side)
			(See <b>POWER WINDOW SUBSWITCH</b>
1			<u>INSPECTION</u> .)
	<ul><li>subswitch (passenger side).</li><li>Does it operate normally?</li></ul>	No	Power window motor
			(See <u>POWER WINDOW MOTOR</u> <u>INSPECTION</u> .)
			Battery (low voltage)
			Inspect the wiring harness between the power
		1	window main switch and the power window
	<ul> <li>Inspect the door glass operation by operating the power window</li> </ul>	res	subswitch (passenger side).  If there is any malfunction, repair or replace the
2	subswitch (passenger side).		applicable part.
	• Does it operate in auto?	No	Perform the power window initialization procedure. (See <b>POWER WINDOW INITIALIZATION</b>
			PROCEDURE .)

# NO.5 DOOR GLASS STOPS BEFORE FULLY OPENING/CLOSING [POWER WINDOW SYSTEMS (EXTERIOR OPEN/CLOSE FUNCTION)]

#### POSSIBLE CAUSE CHART

5	5 DOOR GLASS STOPS BEFORE FULLY OPENING/CLOSING				
POSSIBLE CAUSE	<ul> <li>Power window main switch malfunction</li> <li>Power window subswitch (passenger side) malfunction</li> <li>Power window motor malfunction</li> <li>Battery malfunction (low voltage)</li> <li>Door glass improper installation</li> <li>Power window initialization procedure error</li> <li>Keyless control module malfunction</li> <li>BCM malfunction</li> <li>Keyless entry system signal reception error (outside operation area, radio signal interference)</li> </ul>				

2008 BODY & ACCESSORIES Symptom Troubleshooting [Power Window System (Exterior Open/Close Function)] - Mazda CX-9

Step	Inspection		Action
1	<ul> <li>Operate the door glass in auto/manual by operating the power window main switch/power window subswitch (passenger side).</li> <li>Does the door glass stop before fully opening/closing using either operation?</li> </ul>	Yes	Inspect the following parts, and repair or replace.  • Power window main switch  (See POWER WINDOW MAIN SWITCH INSPECTION .)  • Power window subswitch (passenger side)
2	<ul> <li>Inspect the operation of the door glass by repeating Step 1 above.</li> <li>Does the door glass stop before fully opening/closing while in auto operation?</li> </ul>		Perform the power window initialization procedure. (See <b>POWER WINDOW INITIALIZATION PROCEDURE</b> .)  Go to the next step.
3	<ul> <li>Open the door glass by operating the transmitter.</li> <li>Does the door glass stop before fully opening?</li> </ul>	Yes	Inspect the following parts, and repair or replace.  • Keyless control module (Vehicles with advanced keyless system)  (See KEYLESS CONTROL MODULE INSPECTION [ADVANCED KEYLESS SYSTEM].)  • BCM  (See BODY CONTROL MODULE (BCM) INSPECTION.)  Go to the next step.
			Inspect the following parts, and repair or

2008 BODY & ACCESSORIES Symptom Troubleshooting [Power Window System (Exterior Open/Close Function)] - Mazda CX-9

			replace.
1	<ul> <li>Close the door glass by operating the transmitter.</li> </ul>	Yes	Keyless control module (Vehicle with advanced keyless system)  (See <u>KEYLESS CONTROL</u> MODULE INSPECTION  [ADVANCED KEYLESS      SYSTEM] .)
4	<ul> <li>Does the door glass stop before fully closing?</li> </ul>		BCM (See <u>BODY CONTROL</u> <u>MODULE (BCM) INSPECTION</u> .)      Keyless entry system signal reception error (outside operation area, radio signal interference)
		No	Reinspect for malfunction recurrence. If the malfunction is not corrected, repeat the procedure from Step 1.

# NO.6 DOOR GLASS REVERSES BEFORE IT FULLY OPENS [POWER WINDOW SYSTEMS (EXTERIOR OPEN/CLOSE FUNCTION)]

### POSSIBLE CAUSE CHART

6	Door glass reverses before it fully opens
POSSIBLE CAUSE	<ul><li> Malfunction in power window motor</li><li> Malfunction in battery</li></ul>
	Improper installation of door glass

## **DIAGNOSTIC PROCEDURE**

Step	INSPECTION		ACTION
			Inspect the power window motor and repair or replace it. (See <b>POWER WINDOW MOTOR INSPECTION</b> .)
1	<ul> <li>By operating a power window main switch / power window subswitch (passenger side), operate the door glass.</li> <li>Does the door glass mis-reverse?</li> </ul>	No	Inspect the following parts and repair or replace them.  • Power window motor (See POWER WINDOW MOTOR INSPECTION .)  • Battery (brownout)  • Door glass (improper installation)

2008 BODY & ACCESSORIES Symptom Troubleshooting [Power Window System (Exterior Open/Close Function)] - Mazda CX-9

	NOTE:
	Depending on the temperature, battery, and voltage condition, the door glass may mis-reverse.

# NO.7 DRIVER AND PASSENGER DOOR GLASSES OPERATE ACCIDENTALLY [POWER WINDOW SYSTEMS (EXTERIOR OPEN/CLOSE FUNCTION)]

### POSSIBLE CAUSE CHART

7	Driver and passenger door glasses operate accidentally	
POSSIBLE CAUSE	<ul> <li>Transmitter malfunction</li> <li>Request switch malfunction</li> <li>Open or short circuit in wiring harness between request switch (each door) and keyless control module.</li> <li>Power window main switch malfunction</li> <li>Power window subswitch (passenger side) malfunction</li> <li>Open or short circuit in wiring harness between power window main switch and power window subswitch (passenger side)</li> </ul>	
	BCM malfunction	

#### **DIAGNOSTIC PROCEDURE**

STEP	INSPECTION		ACTION	
		Yes	Inspect the transmitter.	
	Inspect if malfunction is in operating by transmitter		With keyless entry system	
1		No	• Go to Step 3.	
			With advanced keyless system	
			Go to the next step.	
	<ul> <li>Inspect if malfunction is in</li> </ul>		Inspect the following parts and repair or replace.  • Request switch	
2	operating by request switch	Yes	(See <u>REQUEST SWITCH INSPECTION</u> [ADVANCED KEYLESS SYSTEM] .)	
			Wiring harness between request switch and	

2008 BODY & ACCESSORIES Symptom Troubleshooting [Power Window System (Exterior Open/Close Function)] - Mazda CX-9

			keyless control module
		No	Go to the next step.
3	<ul> <li>Inspect if malfunction is in operating power window main switch</li> </ul>	Yes	Inspect power window main switch (See POWER WINDOW MAIN SWITCH INSPECTION .)
	SWITCH	No	Go to the next step.
4	• Inspect if malfunction is in without operating Step 1 to 3	Yes	BCM (See <u>BODY CONTROL MODULE</u> (BCM) INSPECTION .)      Wiring harness between power window subswitch (passenger side) and power window main switch
		No	Reinspect for malfunction recurrence. If the malfunction is not corrected, repeat the procedure from Step 1.

# NO.8 PASSENGER DOOR GLASS OPERATES ACCIDENTALLY [POWER WINDOW SYSTEMS (EXTERIOR OPEN/CLOSE FUNCTION)]

#### POSSIBLE CAUSE CHART

8	Passenger door glass operates accidentally
POSSIBLE CAUSE	Power window subswitch (passenger side) malfunction

#### **DIAGNOSTIC PROCEDURE**

Philotrophic Trace Detail
ACTION
Inspect the power window subswitch of the passenger door glass and repair or replace
(See <b>POWER WINDOW SUBSWITCH INSPECTION</b> .)