

2008 ENGINE

Service Tools (MZI-3.7) - Mazda CX-9

ENGINE SST [MZI-3.7]

1. Mazda SST number
2. Global SST number

Example




Fig. 1: Identifying Service Tools (1 Of 2)
Courtesy of MAZDA MOTORS CORP.

2008 Mazda CX-9 Grand Touring

2008 ENGINE Service Tools (MZI-3.7) - Mazda CX-9
























<p>1: 49 C017 5A0 2: -</p> <p>Engine support set</p> 	<p>1: 49 L017 5A0 2: -</p> <p>Support hanger</p> 	<p>1: 49 UN01 002 2: 303-102</p> <p>Crankshaft damper replacer</p> 
<p>1: 49 G028 203 2: -</p> <p>Support (Component part of 49 F034 2A0)</p> 	<p>1: 49 UN30 3D1210 2: 303-D121</p> <p>Puller</p> 	<p>1: 49 G033 102 2: -</p> <p>Handle</p> 
<p>1: 49 G033 105 2: -</p> <p>Attachment</p> 	<p>1: 49 W026 001 2: -</p> <p>Oil seal installer</p> 	<p>1: 49 UN30 312480 2: 303-1248</p> <p>Hold</p> 
<p>1: 49 W011 101 2: -</p> <p>Oil seal installer</p> 	<p>1: 49 UN30 312523 2: -</p> <p>Installer (Component part of 49 UN30 3125A0)</p> 	<p>1: 49 UN30 312521 2: -</p> <p>Remover (Component part of 49 UN30 3125A0)</p> 
<p>1: 49 N013 101A 2: -</p> <p>Body (Component part of 49 N013 1A0D)</p> 	<p>1: 49 T013 101 2: -</p> <p>Hose</p> 	<p>1: 49 L018 001 2: -</p> <p>O2 sensor wrench</p> 
<p>1: 49 0107 680A 2: -</p> <p>Engine stand</p> 	<p>1: 49 L010 1A0 2: -</p> <p>Engine hanger set</p> 	<p>1: 49 0187 280A 2: -</p> <p>Oil pressure gauge</p> 
<p>1: 49 T018 006 2: -</p> <p>Hose</p> 	<p>1: 49 T018 007 2: -</p> <p>Adapter</p> 	<p>1: 49 9200 145 2: -</p> <p>Radiator cap tester adapter set</p> 
<p>1: 49 B019 901B 2: -</p> <p>Oil pressure gauge (Component part of 49 N013 1A0D)</p> 	<p>1: - 2: 134-01049</p> <p>Evaporative emission system tester</p> 	<p>-</p>

Fig. 2: Identifying Service Tools (2 Of 2)
Courtesy of MAZDA MOTORS CORP.